



POWER DRILL – STUB / 3 x D

PDS ...series



EDP. No.	D	L ₁	L ₂	D ₂	STOCK
PDS010	1	8	38	3	•
PDS011	1.1	10	42		•
PDS012	1.2				•
PDS013	1.3				•
PDS014	1.4				•
PDS015	1.5				•
PDS016	1.6				•
PDS017	1.7				•
PDS018	1.8				•
PDS019	1.9				•
PDS 020	2.0			14	50
PDS 021	2.1	•			
PDS 022	2.2	•			
PDS 023	2.3	•			
PDS 024	2.4	•			
PDS 025	2.5	•			
PDS 026	2.6	•			
PDS 027	2.7	•			
PDS 028	2.8	•			
PDS 029	2.9	•			
PDS 030	3.0	18	60	•	
PDS 031	3.1	22	60	4	•
PDS 032	3.2				•
PDS 033	3.3				•
PDS 034	3.4				•
PDS 035	3.5				•
PDS 036	3.6				•
PDS 037	3.7				•
PDS 038	3.8				•
PDS 039	3.9				•
PDS 040	4.0				•
PDS 041	4.1	24	62	5	•
PDS 042	4.2	26			•
PDS 043	4.3				•
PDS 044	4.4				•
PDS 045	4.5				•
PDS 046	4.6				•
PDS 047	4.7				•
PDS 048	4.8				•
PDS 049	4.9				•
PDS 050	5.0				•
PDS 051	5.1		28	66	6

EDP. No.	D	L ₁	L ₂	D ₂	STOCK	
PDS 052	5.2	28	66	6	•	
PDS 053	5.3				•	
PDS 054	5.4				•	
PDS 055	5.5				•	
PDS 056	5.6				•	
PDS 057	5.7	30	74	7	•	
PDS 058	5.8				•	
PDS 059	5.9				•	
PDS 060	6.0				•	
PDS 061	6.1				•	
PDS 062	6.2	34	74	7	•	
PDS 063	6.3				•	
PDS 064	6.4				•	
PDS 065	6.5				•	
PDS 066	6.6				•	
PDS 067	6.7				37	•
PDS 068	6.8					•
PDS 069	6.9					•
PDS 070	7.0					•
PDS 071	7.1				40	79
PDS 072	7.2	•				
PDS 073	7.3	•				
PDS 074	7.4	•				
PDS 075	7.5	•				
PDS 076	7.6	•				
PDS 077	7.7	•				
PDS 078	7.8	•				
PDS 079	7.9	•				
PDS 080	8.0	•				
PDS 081	8.1	43	84	9	•	
PDS 082	8.2				•	
PDS 083	8.3				•	
PDS 084	8.4				•	
PDS 085	8.5				•	
PDS 086	8.6				•	
PDS 087	8.7				•	
PDS 088	8.8				•	
PDS 089	8.9				•	
PDS 090	9.0				•	
PDS 091	9.1	47	89	10	•	
PDS 092	9.2				•	
PDS 093	9.3				•	

Data • p359